

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

RECEIVED  
JAN 19 2005  
DIV. OF OIL, GAS & MINING

3/5/05

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-04 To (mo./yr.) 12-31-04
2. DOGM File Number (Mine No): 5270029
3. Mine Name: Danny's Mine
4. Mineral(s) Mined (or permitted to mine): Marble
5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
\_\_\_\_ 1/4, SE 1/4, SW 1/4, Section 9, Township 23S, Range 13W  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_ , Township \_\_\_\_ , Range \_\_\_\_  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_ , Township \_\_\_\_ , Range \_\_\_\_
7. Name of Operator or Company: Virginia Gehre Daniel Land
8. Permanent Street Address: 490 E. Canyon Rd POB 875  
City, State, Zip: Fillmore UT 84631  
Phone: 435-743-6501 Fax: \_\_\_\_\_
9. Company Representative (or designated operator):  
Name: VIRGINIA GEHRE  
Title: ~~OPERATOR~~ OWNER  
Business Address: POB 875  
City, State, Zip: Fillmore, UT 84631  
Phone: 435-743-6501 Fax: \_\_\_\_\_  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 5-10 tons

INSPECT

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year  
Surface mined about 8 tons of material for Marble
5. How much **additional** acreage was disturbed during the past year? None
6. How much acreage was **reclaimed** during the past year? Less than 1 Acre
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
Very little surface damage occurred from removing the marble. We replaced earth & tailings as needed.
8. What is the **total** disturbed acreage of entire project at years end? Less than 1 Acre
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
We will continue to remove marble & keep surface damage to a minimum replacing earth & tailings as we proceed.

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.**
2. **The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.**

IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print): VIRGINIA C. GEHRE

Title of Operator: OWNER

Signature of Operator: Virginia C. Gehre

Date: 1-15-05